

TENNESSEE DEPARTMENT OF TRANSPORTATION **EROSION PREVENTION/SEDIMENT CONTROL** INSPECTION REPORT

Reason For Inspection:

1st Weekly

2nd Weekly

3.22.12 DATE:

State Route (SR) / US Ro	ute or Road Name and D	escription:		Are corrective actions				
WOLF RIVER BLVD.					X, NO			
County(ies):	TDOT PIN:	NPDES Permit (NOC)	#:	Number of New	Number of Recurring	Number of New	Number of Un-Corrected	
Shelby	101615	TNR153299	9	Corrective Actions:	Corrective Actions:	Sediment Releases:	Sediment Releases:	
TDOT Construction No.: 7994-1535-54	TDOT Contract No.:	Contractor: Acuff Enterprises Inc.		0	0			
I certify, under penalty of law prepared under my direction designed to assure that quali information presented. Base manage the system, or those information, I cerify that inspe of erosion and sediment cont above. I certify that erosion a	or supervision in accordance fied personnel properly gated on my inquiry of the personsible persons directly responsible tions of storm water discharges have been performed at the control of the contro	ce with a system hered and evaluated on or persons who le for gathering the large points (outfalls) and as recorded in the table	Contractor	rmantown EPSC Inspe Gerald "Jerry" S EPSC Inspector: Tom Acuff	Stanfill	Signature: Signature:		
identified outfall where installed as planned and designed in working order as				f Germantown EPSC Project Manager: Timothy Bierdz		Signature:	The state of the s	
	TDOT EPSC Inspection	on Weekly Rainfall Dat			/	()		


TDOT FPSC Inspection Weekly Rainfall Data Log

		IDOI EPSC	inspectio	n weekiy r	kaintali Dat	a Log				
		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall		TDOT/Contractor Agrees with Inspection Report:
Date	Day of Week	Precipitation	Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO or YES
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, explain and initial:
	Sunday				N/A	N/A	N/A	N/A		
3.19.12	Monday	20			N/A	N/A	N/A	N/A	**	
3.20.12	Tuesday	20	2.20	1.40	N/A	N/A	N/A	N/A	5.0	
3.2/./2	Wednesday	10			N/A	N/A	N/A	N/A		
3.22.12	Thursday	80	0.80	0.70	N/A	N/A	N/A	N/A	5.50	
3.23.12	Friday	30			N/A	N/A	N/A	N/A		
3.24.12	Saturday	30			N/A	N/A	N/A	N/A	00000 A 17 (Aug 0 A 1880) A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
3.25. 12		0			N/A	N/A	N/A	N/A		
	Monday	70.0			N/A	N/A	N/A	N/A		
			**					1900 si		(Additional pages may be attached, if needed)

- "	_			_
Predicted	Pron	בלוחוי	tion	Source.
1 I CUICLEU	1 100	JIVILA	LIOII	Jource.

www.weather.com

Page 1 of **6**_



State/US	Route	or I	7

tate/US Route or Road Name: Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

CONDITION CODES

Date

3/22/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	3/19/2012		22,35	FM,W	Monitoring outfall.
1A	1	21+50	RT	3/19/2012	1	41	FM,W	Backfill in progress at RCBC Pedestrian Underpass.
1B	1	22+00	RT	3/19/2012		12,21,35	FM,W	Backfill in progress at RCBC Pedestrian Underpass.
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,33,35	S,W	Temp. stable.
2A	1	33+50	LT,CL	3/19/2012		12,15,16,42	FM,W	Construction (Test piles) in progress at Abutment #1 @ Bridge #1.
2B	1	35+50	LT	3/19/2012		16,24,42	FM,W	Construction (Test piles) in preparation Abutment #2 @ Bridge #1. Weekly cleaning for stream crossing as required.
3	1	34+50	LT	10/27/2011		16	FM,W	Outfall slopes north of temp. stream crossing are showing signs of failure.
4	1	40+00	RT	12/12/2011	T = 10-24-11	15,16,43	S,W	Temp. stable.
5A	1	49+00	RT	3/19/2012		16,24,33	FM,W	Monitoring RSS (Rock Silt Screen) in place. Weekly cleaning for stream crossing as required. Repair SFB as required.
5B	1	50+00	RT	3/19/2012		9,16,33	FM,W	Continue construction of proposed RCBC.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 2 Temporary Mulch Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 **Erosion Control Blanket** Ditch Liner R Replacement Needed Rock Check Dams 4 18 Flexible Channel Liner Rock Silt Screen FM Future Maintenance **Brush Barrier** 5 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure Enhanced Silt Fence 1 Increase Measures 7 Straw Bale Check Riprap Energy / Velocity Dissipater 21 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion Sheet Pilling CM Corrections currently being made 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O31): 14 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 42 **Bridge Construction** Other (O#2): Stream Realignment Other (O#3):

State/US Route or Ro

ad Name:

Wolf	River	Blvd.	
------	-------	-------	--

TDOT Construction No.: 79954-3537-54

TDOT Contract No.:		
I DO I CONGACTIVO		

Date	3/22/2012	
Date	3/22/2012	

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	3/15/2012		16,33	FM,W	Monitoring temp. BMP's.
6	1	56+00	LT	3/19/2012		16,35	FM,W	No activity. Monitoring BMP's.
7	1	60+00	RT	10/24/2011		16, 33	S,W	Temp. stable.
8A	1	73+00	RT	3/19/2012		16,24,42	FM,W	Weekly cleaning for stream crossing will be required, until further notice. No Bridge activity.
8B	2	75+50	RT	3/19/2012		4,16,35,41	FM,W	Monitoring temp. BMP's.
8C	1	71+00	LT	2/21/2012	P = 2-21-12 riprap installed at Bridge 2, East Bank	16,35,42	S,W	Monitoring temp. BMP's @ Bridge 2, Abutment 1 rip rap on west bank.
8D	2	75+50	LT	2/9/2012	P = 2-2-12 riprap installed at Bridge 2, East Bank	12,16,35,42	FM,W	Monitoring temp. BMP's @ Bridge 2, Abutment 2 rip rap east bank.
8E	1	71+50	LT, RT or CL	3/15/2012		12,42	FM,W	Continue Rip Rap installation under Bridge as per plans. No Bridge activity.
9A	2	80+00	RT	9/29/2011	T = 10-3-11	6,15,33,35	S,W	Temp. stable.
9B	2	80+00	LT	9/29/2011	T = 10-3-11	15,16,17,,35	S,W	Temp. stable.

EROSION AND SEDIMENT CONTROL MEASURE CODES

CONDITION CODES Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 4 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance Brush Barrier 5 19 Calch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 6 20 Riprap Outlet Structure **Enhanced Silt Fence** 1 Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater Sediment Tube 35 W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence Temporary at Construction Exit / Entrance 9 Sediment Trap / Basin 23 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion Sheet Pilling CM Corrections currently being made 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O31): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#2): Other (O#3):

State/US	Route	or Ro

IS Route or Road Name:	Wolf River Blvd.

TDOT	Construction	Ne

70054	0507 54	
79954	-3537-54	ı,

TDOT	Contract No.:		

Date	3/22/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	FM,W	Monitoring lemp. BMP's.
10A	2	85+00	RT	3/1/2012		3,15,16,35,41	S,W	Temp. stable.
10B	2	85+00	RT	3/15/2012		3,15,16,35,41	S,W	Temp. stable.
10C	2	85+50	LT	11/14/2011		3,15,16,35,41	s,w	Temp. stable.
10D	2	84+50	LT	1/6/2012	,	3,15,16,35,41	FM,W	Monitoring temp. BMP's.
11A	2	92+50	RT	3/1/2012		3,35,41	FM,W	Monitoring temp. BMP's.
11B	2	92+50	LT	1/6/2012	T = 01-10-12	10,32,35,41	S,W	Monitoring temp. BMP's.
11C	2	92+00	LT	1/6/2012	T = 01-10-12	10,32,35,41	S,W	Monitoring temp. BMP's.
	1	11+28	LT	3/19/2012		19,35	FM,W	Daily cleaning is required, until further notice.
	1	13+40	RT	3/19/2012		23,29,30	FM,W	Daily cleaning will be required, until further notice.
	1	107+75	CL N AND SEDIME	3/19/2012	MEASURE CODES	23,29,30	FM,W	Daily cleaning will be required, until further notice. CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy, Daily M Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) 30 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner Rock Silt Screen FM Future Maintenance 32 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing Cleaning Needed Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 7 W Too Wet to Work Conditions 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion Stable (No Action Needed) Machined Rip Rap CM 12 26 Temporary Stream Diversion 40 Sheet Pilling Corrections currently being made Geotextile 13 27 Preserve Natural Resource / Buffer Zone Haul Road Other (O31): Permanent Seeding with Mulch or Sod 14 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#2): Other (O#3):

State/US Route or Road Nar	me:
----------------------------	-----

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	3/22/2012

		2			Date of	Existing		
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
(Existing	No.	From / To			T = Temp.	Measure	Codes	
Structure)					P = Perm.	Codes*		
* 400 . 54		E (: (() () ()						Daily cleaning will be required, until further
* 109+51	2	East side of WRB	RT	3/19/2012		19,22	FM,W	notice.
		South side of						Daily cleaning will be required, until further
* 109+11	2	Farmington	RT	3/19/2012		19,22	FM,W	notice.
* 40.00		North side of						Daily cleaning will be required, until further
* 12+80	1	WRB	LT	3/19/2012		19,22	FM,W	notice.
		Walking Trail						
	11	36+00	LT	7/20/2011	T = 7-20-11	5,35	S,W	Temp. stable.
		Sta. 29+50						
	11	Slope	LT	7/20/2011	T= 9-01-11	16	S,W	Temp. stable.
		Sta. 13+40 -						Haul roads dampened frequently for dust
	1 & 2	Sta. 107+75	LT, RT or CL	3/19/2012		3,30,38	FM,W	control, until further notice.

	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	3,15,16,35,38	S,W	Temp. stable.
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	3,15,16,35,38	S,W	Temp. stable.
								Daily cleaning will be required, until further
	1	6+75	LT	3/19/2012		19,22	FM,W	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	S,W	Temp. stable.
	1	34+00	RT	8/25/2011	T= 8-25-11	16	S,W	Temp. stable.
		EROSI	ON AND SEDIMEN	T CONTROL ME	ASURE CODES	•		CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 **Brush Barrier** 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin 9 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 38 **Temporary Stream Crossing** Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 40 **Temporary Stream Diversion** Sheet Pilling CM Corrections currently being made 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Other (O31): 41 Haul Road Permanent Seeding with Mulch or Sod 28 Other (O#2): Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

HE	٠.
XY >	<i>.</i>
CHI TUR	
47	劉
MERC	

Wolf River Blvd. State/US Route or Road Name: TDOT Construction No.: 79954-3537-54 TDOT Contract No.:

> Date 3/22/2012

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
	1	21+33 - 26+00	LT	2/2/2011	T = 10-6-11	3,15,16,33,35, 38,41	S,W	Temp. stable.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	3,15,16,33,35, 38,41	S,W	Temp. stable.
	1	25+00	LT	3/15/2012	T = 10-6-11	15,16,33,35,41	FM,W	Install Culvert Protection Type 1. See previous report for photo.
	11	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	S,W	Temp. stable.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	S,W	Temp. stable.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	S,W	Temp. stable.
11-24120	1	15+60	LT & RT	3/15/2012		15,16,33,35	FM,W	Monitoring temp. BMP's.
* 108+37	2	North side of WRB	LT	3/19/2012		19,22	FM,W	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	S,W	Temp. stable.
	1	25+00	RT	3/19/2012		15,33,35	S,W	Corrections made. Monitoring temp. BMP's.
7	1	44+00	LT,CL,RT	3/1/2012		33	FM,W	Repair SFB as required. See previous report for photo.
		EROSIO	N AND SEDIME	NT CONTROL N	MEASURE CODES			CONDITION CODES

SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily 29 M Mainlenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing С Cleaning Needed Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Repeat Occurrence 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release SR Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 S 11 Gabion Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion 40 Sheet Pilling CM Corrections currently being made 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O31): Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Sub grade Bridge Construction Other (O#2): Other (O#3):